



BMW SERIE 3 TOURING: 1KXE217

Vinnumber:	WBA3L11010K175898	Versionname:	320D
First Registrationdate:	22/07/2015	Fiscalpower:	
Expertise Mileage:	76901	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4401
Maintenance:	IN 5000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1525,15
-------------------	----------------

Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Tires, Out of tolerance, P - Check 0,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Mirror side blinker L, Broken, E - Replace 30,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Broken, Le - Replace and paint 735,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s), PDR - Paintless dent repair 63,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 283,80





Tailgate, Scratch(es), Acceptable

0,00

No pictures to display