



CITROEN C4 Picasso: 1GVB813

Vinnumber:	VF73A9HC8EJ635146	Versionname:	GR.C4 PICASSO Intensive 115PK
First Registrationdate:	8/05/2014	Fiscalpower:	
Expertise Mileage:	190700	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3223
Maintenance:	5.400 KM OU 9 MOIS		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1086,87
Door F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Armrest F Mid, Worn, Smart repair	64,32



Boot cover, Broken, Forfeit

15,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Repaired, Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Dent(s), Acceptable

0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

404,20



Tailgate, Crack, Le - Replace and paint

0,00





Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00

