



CHEVROLET Captiva: 1EDG227

Vinnumber:	KL1CF2699BB109018	Versionname:	CAPTIVA LT FWD 163PK
First Registrationdate:	10/01/2012	Fiscalpower:	
Expertise Mileage:	108215	Power Kw:	120
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2809
Maintenance:	GEEN INDICATIE		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/60/17/102 H LightMetal				
Summer tyres:	Fr.L.	Hankook: 3 mm	Fr.R.	Hankook: 3 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	373,36
-------------------	---------------

Door F L, Dent(s), PDR - Paintless dent repair	63,00
--	--------------



Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Seat cover F L, Stain, Cleaning	25,00
---------------------------------	-------



Mirror side blinker R, Broken, E - Replace	31,20
--	-------



Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

