



BMW X3: ME9250			
Vinnumber:	WBAWZ510200M08072	Versionname:	X3 2.0d xDrive20 190PK
First Registrationdate:	11/05/2015	Fiscalpower:	
Expertise Mileage:	134044	Power Kw:	140
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1126
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/60/17/99 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			382,02
Bumper R, Scratch(es), 67 - Polish			0,00
<i>No pictures to display</i>			
Bonnet, Chemical polution, 67 - Polish			0,00
<i>No pictures to display</i>			
Door R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			



No pictures to display