



CITROEN Jumpy: FK6012

Vinnumber:	VF7XUAHZ8EZ009918	Versionname:	JUMPY B/F MWB L2H1 Fresh 1200kg 128PK
First Registrationdate:	4/04/2014	Fiscalpower:	
Expertise Mileage:	93710	Power Kw:	94
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2705
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/103 T Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1539,35
-------------------	---------

Windscreen, Crack, E - Replace	395,40
--------------------------------	--------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------



Trunk door panel L, Missing, E - Replace	20,00
--	-------



Bonnet, Dent(s), PDR - Paintless dent repair	122,40
--	--------



Trunk door panel L, Hole, E - Replace	44,00
---------------------------------------	-------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	231,15
---	--------



Interior, Dirty, Cleaning	0,00
---------------------------	------



Trunk door R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Scratch(es), Smart repair	110,64
-------------------------------------	--------



Trunk door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,88

