



MERCEDES C: 1GQI713

| | | | |
|-----------------------------------|--------------------------|--------------|---|
| Vinnumber: | WDD2042011G138211 | Versionname: | C BRE 200 CDI BlueEFF. S&S 136PK |
| First Registrationdate: | 1/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 152512 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance | OVER 17200 KM | | |
| Maintenance | OK | | |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | | |
|--------------------------------|-----------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | HD | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining semi-leather | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 225/45/17/91 W LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 2 mm | Fr.R. | Continental: 2 mm |
| | Re.L. | Bridgestone: 3 mm | Re.R. | Bridgestone: 3 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 285,00 |
|-------------------|---------------|

| | |
|--|--------------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|



| | |
|--|-------|
| Door R L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Trunk lid covering R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Internal Boot Lining L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Sill trim L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|--|-------|
| Wing R R, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |

