



DODGE RAM: 1DYE011

Vinnumber:	1C6RR7MT4E5291955	Versionname:	
First Registrationdate:	19/01/2015	Fiscalpower:	
Expertise Mileage:	113515	Power Kw:	295
Bodytype:	Transporter	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV24
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Seats F L ventilated	
Steering wheel multifunctional		Seats F R ventilated	
Seats F heated		Sun Roof electric	
Type of headlighting	Headlighting Halogen	Central consol F	
Type of GPS	GPS big screen color	Front parking sensors	
Type of Lining	Lining leather	Rear parking sensors	
Type of climate control	Autom climate control	Type of Tow bar	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	275/60/20/115 R LightMetal			
Winter tyres:	Fr.L.	Other: 4 mm	Fr.R.	Other: 4 mm
	Re.L.	Other: 8 mm	Re.R.	Other: 8 mm

Assistance equipment

Total cost ex VAT	5529,24
Rearlight R , Broken, E - Replace	91,50



Sill outer R, Dent(s), PDR - Paintless dent repair	63,00
--	--------------



Rearview mirror housing L, Broken, E - Replace 44,00



Wing R R, Dent(s) and scratch(es), Le - Replace and paint 983,63



Door F R, Dent(s) and scratch(es), Le - Replace and paint 847,88



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing F R, Dent(s) and scratch(es), Le - Replace and paint 427,51



Bumper F, Broken, Le - Replace and paint 575,25



Protection plate M, Tear, E - Replace 74,00



Rearview mirror R complete, Missing, Le - Replace and paint 253,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

231,15



Roof pillar L, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,14



Door R R, Dent(s) and scratch(es), Le - Replace and paint

746,18



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

158,85



Aerial, Damaged, E - Replace

11,25



Interior, Dirty, Cleaning

150,00





Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Roof pillar R, Dent(s) and scratch(es), LI - Repair and paint (complete)

213,14



Tyre F R, Tear, E - Replace

105,00

