



RENAULT Clio: 1GQZ821

Vinnumber:	VF17R040H50623746	Versionname:	CLIO IV BRE Business 75PK
First Registrationdate:	4/04/2014	Fiscalpower:	
Expertise Mileage:	194575	Power Kw:	55
Bodytype:	Break	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2730
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	664,80
-------------------	--------

Bumper corner R R, Scratch(es), It - Spot repair	115,56
--	--------



Wheel cover F R, Deformed / Strained, E - Replace 24,00



Windscreen, Scratch(es), E - Replace 0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Wheel cover R R, Deformed / Strained, E - Replace 24,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display