


**RENAULT CLIO: 1KBH845**

|                                    |                          |              |                                      |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber:                         | <b>VF15RJL0H52519254</b> | Versionname: | <b>1.5 ENERGY DCI 90E EXPRESSION</b> |
| First Registrationdate:            | <b>25/03/2015</b>        | Fiscalpower: |                                      |
| Expertise Mileage:                 | <b>117114</b>            | Power Kw:    | <b>66</b>                            |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Silver</b>                        |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                       |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                         |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                            |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1714</b>                          |
| Number of doors:                   | <b>5</b>                 |              |                                      |
| Number of seats:                   | <b>5</b>                 |              |                                      |
| Number head rests:                 | <b>5</b>                 |              |                                      |
| Rims summer:                       | <b>Steel</b>             |              |                                      |
| Category:                          | <b>Passenger Car</b>     |              |                                      |
| Oil level:                         | <b>OK</b>                |              |                                      |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                      |

**Options**

|                                |                               |                   |
|--------------------------------|-------------------------------|-------------------|
| Radio CD                       | Luggage cover                 |                   |
| Windows electric F             | Type of Tow bar               | <b>No Tow bar</b> |
| Cruise Control                 |                               |                   |
| Steering wheel multifunctional |                               |                   |
| Radio multimedia               |                               |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                   |
| Type of GPS                    | <b>GPS big screen color</b>   |                   |
| Type of Lining                 | <b>Lining fabrics</b>         |                   |
| Type of climate control        | <b>Manual climate control</b> |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
|               | <b>185/65/15/92 T Steel</b> |                       |       |                       |
| Summer tyres: | Fr.L.                       | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                       | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|   |       |
|---|-------|
| Total cost ex VAT                                 | 96,00 |
| Wheel cover R L, Deformed / Strained, E - Replace | 24,00 |



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 24,00



Wheel cover F L, Scratch(es), E - Replace 24,00

