



MERCEDES C BREAK: 1LEJ517

Vinnumber:	WDD2052361F266866	Versionname:	1.6 C 180 BLUETEC
First Registrationdate:	4/09/2015	Fiscalpower:	
Expertise Mileage:	176878	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4111
Maintenance:	ASS A PLUS 2900 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	522,30
-------------------	---------------

Door R L, Dent(s), Acceptable	0,00
-------------------------------	-------------



Maintenance, Maintenance, P - Check

0,00



Sill outer R, Deformed / Strained, LI - Repair and paint (complete)

310,50



Bonnet, Chemical polition, 67 - Polish

0,00



Wing R L, Dent(s), Acceptable

0,00



Door R R, Dent(s), Acceptable

0,00



Wing R R, Dent(s), Acceptable

0,00



Windscreen, Repaired, P - Check

0,00



Bumper R, Scratch(es), Acceptable

0,00



Backrest cover F L, Worn, P - Check

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

