



RENAULT Clio: YD4022

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnnummer: | VF15RFL0H51628128 | Versionname: | CLIO IV BER Expression St&St 90PK |
| First Registrationdate: | 27/08/2014 | Fiscalpower: | |
| Expertise Mileage: | 174747 | Power Kw: | 66 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4715 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | | |
|--------------------------------|-------------------------------|-----------------|-------------------|
| GPS storage | | Luggage cover | |
| GPS storage | HD | Type of Tow bar | No Tow bar |
| Windows electric F | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|---------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | NOT OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 185/65/15/88 T Steel | | | |
| Winter tyres: | Fr.L. | Goodyear: 4 mm | Fr.R. | Goodyear: 4 mm |
| | Re.L. | Other: 7 mm | Re.R. | Other: 7 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 470,08 |
|-------------------|---------------|

| | |
|---|---------------|
| Certificate Of Conformity, Missing, E - Replace | 150,00 |
|---|---------------|

No pictures to display

| | |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|-------------------------------|-------------|
| Door F R, Dent(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display

wheel cover F R, Broken, E - Replace

30,00



Tailgate, Scratch(es), 67 - Polish

0,00

No pictures to display

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

290,08

