



SKODA OCTAVIA COMBI: 1LNE932

Vinnumber:	TMBLG7NE1G0100737	Versionname:	1.6 CRTDI 81KW 4WD GREENTEC AMBITION
First Registrationdate:	27/10/2015	Fiscalpower:	
Expertise Mileage:	154404	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2509
Maintenance:	OVER 18600 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1748,21
Wheel cover R R, Missing, E - Replace	30,00



Wheel arch cover F R, Broken, E - Replace

48,84



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Wheel cover F L, Missing, E - Replace

30,00



Seat cover F L, Stain, Cleaning

25,00



Seat cover F R, Stain, Cleaning

25,00



Wheel cover R L, Missing, E - Replace

30,00



Wing F L, Dent(s), LI - Repair and paint (complete)

268,18



Wheel cover F R, Missing, E - Replace

30,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

414,35



Wheel arch cover F L, Broken, E - Replace

48,84



Bumper F, Broken, Le - Replace and paint

735,00



Windscreen, Stone chip(s), E - Replace

0,00

