



**VOLKSWAGEN Caddy: 1GRA659**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>WV1ZZZ2KZEX116548</b> | Versionname: | <b>CADDY MAXI VAN B/F DSG 105PK Aut.</b> |
| First Registrationdate:            | <b>4/04/2014</b>         | Fiscalpower: |  |
| Expertise Mileage:                 | <b>78713</b>             | Power Kw:    | <b>75</b>                                |
| Bodytype:                          |                          | Body color:  | <b>White</b>                             |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Opaque</b>                            |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                             |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                |
| Maintenance:                       | <b>NOT OK</b>            | Parking lot: | <b>3310</b>                              |
| Battery functioning:               | <b>Yes</b>               |              |  |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>2</b>                 |              |  |
| Number head rests:                 | <b>2</b>                 |              |  |
| Rims summer:                       | <b>Steel</b>             |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                         |                                  |
|-------------------------|----------------------------------|
| Radio CD                |                                  |
| Windows electric F      |                                  |
| Radio multimedia        |                                  |
| Type of headlighting    | <b>Headlighting Halogen</b>      |
| Type of GPS             | <b>No GPS</b>                    |
| Type of Lining          | <b>Lining artificial leather</b> |
| Type of climate control | <b>Manual climate control</b>    |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                          |       |                          |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
|               | <b>195/65/15/95 T Steel</b> |                          |       |                          |
| Summer tyres: | Fr.L.                       | <b>Bridgestone: 6 mm</b> | Fr.R. | <b>Bridgestone: 7 mm</b> |
|               | Re.L.                       | <b>Goodyear: 6 mm</b>    | Re.R. | <b>Goodyear: 6 mm</b>    |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                   |                |
|-------------------|----------------|
| Total cost ex VAT | <b>1171,08</b> |
|-------------------|----------------|

|                                   |             |
|-----------------------------------|-------------|
| Maintenance, Maintenance, Execute | <b>0,00</b> |
|-----------------------------------|-------------|



|   |             |
|---|-------------|
| Bodywork, Not original part, Acceptable | <b>0,00</b> |
|---|-------------|



Sill outer R, Dent(s), LI - Repair and paint (complete)

372,60



Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84



Windscreen, Stone chip(s), Windscreen repair

58,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84

