


SKODA Octavia: 1FXW336

Vinnumber:	TMBJG7NE4E0108917	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	2/12/2013	Fiscalpower:	
Expertise Mileage:	104453	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4828
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar removable
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	205/55/16/92 V Steel			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2550,23
Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Missing, E - Replace 30,00



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover R R, Missing, E - Replace 30,00



Sill outer L, Dent(s), LI - Repair and paint (complete) 310,50



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Dent(s), LI - Repair and paint (complete) 318,35



Wheel cover F L, Missing, E - Replace

30,00



Wheel cover F R, Scratch(es), E - Replace

30,00



Rearlight L, Crack, E - Replace

114,00



Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50

