



VOLKSWAGEN PASSAT VARIANT: 1KBT321

Vinnumber:	VVWZZZ3CZFE478419	Versionname:	1.6 TDI VARIANT COMFORTLINE DSG
First Registrationdate:	26/03/2015	Fiscalpower:	88
Expertise Mileage:	108663	Power Kw:	88
Bodytype:	Break	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4210
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 MS LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	785,44
-------------------	---------------

Ignition key, Missing, E - Replace	0,00
------------------------------------	-------------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper R. Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Bumper F R, Scratch(es), It - Spot repair

115,56



Rocker panel inner F L, Dent(s), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror R complete, Broken, E - Replace

168,00



Bonnet, Chemical pollution, LI - Repair and paint (complete)

290,08

