



**VOLVO V70: 1GQF741**

Vinnumber:	<b>YV1BW8481E1305094</b>	Versionname:	<b>V70 D2 Polar 115PK</b>
First Registrationdate:	<b>1/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>106391</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2813</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>No Tow bar</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

Winter tyres:	<b>205/60/16/92 H LightMetal</b>			
	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>95,00</b>
-------------------	--------------

Alloy rim R R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Bumper R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

*No pictures to display*

Wiper Blade R, Damaged, E - Replace	0,00
-------------------------------------	------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

*No pictures to display*

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*