



BMW 1: LA6103

Vinnumber:	WBA1C11020P530832	Versionname:	1 BER HATCH 118d 143PK
First Registrationdate:	25/11/2014	Fiscalpower:	
Expertise Mileage:	71320	Power Kw:	105
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1309
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1049,41
Bonnet, Bad repair, Acceptable	0,00



Wheel hub cap R R, Missing, E - Replace

15,00



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Sill outer R, Scratch(es), It - Spot repair

115,56



Wheel hub cap F L, Missing, E - Replace

15,00



Parking sensor R, Missing, E - Replace

74,00



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel hub cap F R, Missing, E - Replace

15,00



Wheel hub cap R L, Missing, E - Replace

15,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display