



FORD GRAND TOURNEO CONNECT: 1KPC853

Vinnumber:	WF0UXXWPGUFL10975	Versionname:	1.6 ECOBOOST 112KW AUTO TITANIUM
First Registrationdate:	8/06/2015	Fiscalpower:	
Expertise Mileage:	164645	Power Kw:	110
Bodytype:	MPV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2505
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H LightMetal				
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Total cost ex VAT	1605,61
Door R R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), LI - Repair and paint (complete)	165,13



Tailgate, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

158,85



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Internal Boot Lining L, Scratch(es), Smart repair

110,64



Internal Boot Lining R, Scratch(es), Smart repair

110,64



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

158,85



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Ignition key, Missing, E - Replace 150,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64

