



MERCEDES GLA 180: 1KBD930

Vinnumber:	WDC1569121J124097	Versionname:	CDI
First Registrationdate:	24/03/2015	Fiscalpower:	
Expertise Mileage:	41874	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	B5 OVER 60 DAGEN	Parking lot:	3332
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/50/18/101 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	510,33
-------------------	---------------


Bumper F, Dent(s) and scratch(es), It - Spot repair	115,56
-----------------------------------------------------	---------------



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing moulding F R, Scratch(es), E - Replace 17,28



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 360,21



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F R, Scratch(es), E - Replace 17,28



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), 67 - Polish 0,00

