



LU Mercedes Vito: UJ9096

Vinnumber:	WDF44760113070160	Versionname:	1.6 CDI 84KW 111CDI SWB COMPACT
First Registrationdate:	13/07/2015	Fiscalpower:	
Expertise Mileage:	164465	Power Kw:	84
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	NOT OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/16/100 T Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1642,58
-------------------	----------------

Rearview mirror housing L, Scratch(es), Acceptable	0,00
----------------------------------------------------	-------------

No pictures to display

Door R R, Dent(s), LI - Repair and paint (complete)	310,76
-----------------------------------------------------	---------------





Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

458,02



Wing R L, Repaired, Acceptable

0,00

No pictures to display

Interior, Stain, Cleaning

25,00



Windscreen, Stone chip(s), E - Replace

395,40



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Bodywork, Not original part, Remove lettering

0,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), E - Replace

329,40





Rearview mirror housing R, Scratch(es), E - Replace

124,00



Rear bulkhead lining, Scratch(es), Acceptable

0,00

No pictures to display