


**VOLVO XC60: 1HXF660**

|                                    |                          |              |                              |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnumber:                         | <b>YV1DZ31A1F2676291</b> | Versionname: | <b>XC60 D3 Kinetic 136PK</b> |
| First Registrationdate:            | <b>20/10/2014</b>        | Fiscalpower: |                              |
| Expertise Mileage:                 | <b>110405</b>            | Power Kw:    | <b>100</b>                   |
| Bodytype:                          | <b>SUV</b>               | Body color:  | <b>Black</b>                 |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>               |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>             |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                    |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2512</b>                  |
| Number of doors:                   | <b>5</b>                 |              |                              |
| Number of seats:                   | <b>5</b>                 |              |                              |
| Number head rests:                 | <b>5</b>                 |              |                              |
| Rims summer:                       | <b>Aluminium</b>         |              |                              |
| Category:                          | <b>Passenger Car</b>     |              |                              |
| Oil level:                         | <b>OK</b>                |              |                              |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                              |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 | Type of Tow bar              |
| Steering wheel multifunctional | <b>Tow bar fixed</b>         |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |
| Sport seats                    |                              |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                      |       |                      |
|---------------|-----------------------------------|----------------------|-------|----------------------|
|               | <b>235/65/17/108 H LightMetal</b> |                      |       |                      |
| Winter tyres: | Fr.L.                             | <b>Dunlop: 4 mm</b>  | Fr.R. | <b>Dunlop: 4 mm</b>  |
|               | Re.L.                             | <b>Pirelli: 5 mm</b> | Re.R. | <b>Pirelli: 5 mm</b> |

**Assistance equipment**

|                                                         |            |            |                |
|---------------------------------------------------------|------------|------------|----------------|
| Repair kit                                              | <b>Yes</b> | Compressor | <b>Yes</b>     |
| Total cost ex VAT                                       |            |            | <b>2234,78</b> |
| Wing R L, Dent(s), Acceptable                           |            |            | <b>0,00</b>    |
| <i>No pictures to display</i>                           |            |            |                |
| Door F L, Scratch(es), Acceptable                       |            |            | <b>0,00</b>    |
| <i>No pictures to display</i>                           |            |            |                |
| Bumper F, Scratch(es), LI - Repair and paint (complete) |            |            | <b>254,16</b>  |



Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), LI - Repair and paint (complete) 382,02





Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Door R L, Scratch(es), LI - Repair and paint (complete)

382,02



Bumper F, Scratch(es), It - Spot repair

115,56

