



VOLVO V40: 1HXX363

Vinnumber:	YV1MV5151F2205547	Versionname:	V40 D3 Base 150PK
First Registrationdate:	24/10/2014	Fiscalpower:	
Expertise Mileage:	114246	Power Kw:	110
Bodytype:	Break	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2214
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H Steel			
Winter tyres:	Fr.L. Uniroyal: 4 mm	Fr.R. Uniroyal: 4 mm	
	Re.L. Uniroyal: 4 mm	Re.R. Uniroyal: 4 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	993,35
Mirror side blinker R, Broken, E - Replace	30,00




Rear window, Scratch(es), E - Replace

370,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Hail damage, PDR - Hail

125,00



Ignition key, Missing, E - Replace

150,00

No pictures to display