



VOLKSWAGEN Crafter 35 MWB hoog dak: RM9903

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber: | WV1ZZZ2EZE6017104 | Versionname: | CRAFTER 35 B/F MWB HR 136PK |
| First Registrationdate: | 4/02/2016 | Fiscalpower: | |
| Expertise Mileage: | 262209 | Power Kw: | 100 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Opaque |
| Transmission: | Back | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | LCV15 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 2 | | |
| Number head rests: | 2 | | |
| Rims summer: | Steel | | |
| Category: | VS | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | |
|-------------------------|----------------------------------|----------------------|
| Radio CD | Central consol F | |
| GPS storage | Type of Tow bar | Tow bar fixed |
| GPS storage | | HD |
| Windows electric F | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining artificial leather | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|------------------------------|-------------------------|-------|-------------------------|
| | 235/65/16/118 R Steel | | | |
| Winter tyres: | Fr.L. | Vredestein: 7 mm | Fr.R. | Vredestein: 7 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 737,17 |
|-------------------|---------------|

| | |
|---|---------------|
| Wing R L, Dent(s), LI - Repair and paint (complete) | 231,15 |
|---|---------------|



Central pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00



Grill, Scratch(es), LI - Repair and paint (complete) 124,00



Sliding door R, Dent(s), LI - Repair and paint (complete) 382,02



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display