



**SEAT Leon: 1GPU480**

Vinnumber:	<b>VSSZZZ5FZER096139</b>	Versionname:	<b>LEON ST Style 105PK</b>
First Registrationdate:	<b>27/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>130675</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2824</b>
Maintenance:	<b>IN 9000 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 T LightMetal</b>				
Winter tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>410,74</b>
Rearview mirror housing R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Seat adjuster F L, Broken, E - Replace	<b>12,00</b>



Door R R, Dent(s), PDR - Paintless dent repair

63,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Door F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F R, Scratch(es), It - Spot repair

115,56

