



VOLKSWAGEN Crafter 32 MWB hoog dak: 1GXJ525

Vinnumber:	WV1ZZZ2ZE6020416	Versionname:	CRAFTER 32 B/F MWB HR 136PK
First Registrationdate:	27/05/2014	Fiscalpower:	
Expertise Mileage:	107394	Power Kw:	100
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV09
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Front parking sensors	
Windows electric F		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/16/113 R Steel			
Winter tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Firestone: 5 mm	Re.R.	Firestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	407,56
Side bar R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Mirror side blinker R, Crack, E - Replace	28,50



Door moulding Lower R R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R R, Dent(s) and scratch(es), It - Spot repair 115,56



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Door moulding Lower R L, Scratch(es), E - Replace 91,50



Bumper R, Deformed / Strained, E - Replace 172,00

