



RENAULT CLIO GRANDTOUR: 1PDG795

Vinnumber:	VF17RBF0A55200805	Versionname:	1.5 ENERGY DCI 75 EXPRESSION
First Registrationdate:	9/06/2016	Fiscalpower:	
Expertise Mileage:	200507	Power Kw:	55
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	3329
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/88 T Steel				
Winter tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2479,96
Wheel cover F R, Crack, E - Replace			30,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Seat cover F L, Hole, E - Replace 360,00



Wheel cover R L, Missing, E - Replace 30,00



Door R L, Dent(s), LI - Repair and paint (complete) 318,35



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Wing R L, Dent(s), LI - Repair and paint (complete) 308,20



Door R R, Dent(s), LI - Repair and paint (complete) 318,35



Tyre R R, Flat, E - Replace 132,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Missing, E - Replace 30,00



Engine protective plate, Deformed / Strained, E - Replace 69,20



Bumper F, Stone chip(s), LI - Repair and paint (complete)

211,80




Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Roof, Dent(s), LI - Repair and paint (complete)

481,50



Interior, Stain, Cleaning

75,00

