



OPEL Movano 3500 MWB Med.High Roof: 1GEZ737

Vinnumber:	WOLMRFESCEB049306	Versionname:	MOVANO 3500 B/F L2H2 ecoFL.(E5)125PK
First Registrationdate:	21/01/2014	Fiscalpower:	
Expertise Mileage:	46767	Power Kw:	92
Bodytype:	Transporter	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV16
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/65/16/112 R Steel				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Total cost ex VAT	1421,12
Wing F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), LI - Repair and paint (complete)	231,15



Rearview mirror L complete, Scratch(es), E - Replace 138,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Rearview mirror R complete, Broken, E - Replace 138,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Floor covering F L, Hole, E - Replace 237,00



Sidewall FR (LCV), Dent(s) and scratch(es), It - Spot repair 115,56



Trunk door R R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Rearlight L, Broken, E - Replace 04,50

