



VOLVO V60: 1JJV915

Vinnumber:	VV1FW31A1F1253779	Versionname:	2.0 D3 KINETIC
First Registrationdate:	6/01/2015	Fiscalpower:	
Expertise Mileage:	95995	Power Kw:	100
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 17801 KM	Parking lot:	2210
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
TV/DVD screen F		Luggage cover	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 W LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1160,60
Seat cover F R, Stain, Cleaning			25,00



Wing R R, Scratch(es), Acceptable

0,00



Door R L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Maintenance book, Missing, E - Replace

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Hail damage, LI - Repair and paint (complete)

0,00



Door panel R L, Tear, E - Replace

114,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror L complete, Broken, E - Replace

168,00



Seat cover R, Stain, Cleaning

50,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Dent(s), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

