



VOLKSWAGEN Crafter 35 MWB hoog dak: 1FLC530

Vinnumber:	WV1ZZZ2EZD6024869	Versionname:	CRAFTER 35 B/F MWB HR 109PK
First Registrationdate:	2/08/2013	Fiscalpower:	
Expertise Mileage:	111616	Power Kw:	80
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV19
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/16/115 T Steel				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	587,15
-------------------	---------------

Windscreen, Stone chip(s), Windscreen repair	58,80
--	--------------



Seat cover F L, Hole, Smart repair

64,32



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Wing R R, Rust, LI - Repair and paint (complete)	231,15
--	--------



Sill outer L, Scratch(es), LI - Repair and paint (complete)	232,88
---	--------

