



VOLKSWAGEN PASSAT VARIANT: 1LTL301

Vinnumber:	WVWZZZ3CZGE122263	Versionname:	2.0 TDI SCR 140KW MSQ VARIANT HIGHLINE
First Registrationdate:	1/12/2015	Fiscalpower:	
Expertise Mileage:	171154	Power Kw:	140
Bodytype:	Break	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3730
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Sun Roof electric
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/17/98 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 1 mm	Fr.R.	Bridgestone: 1 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	612,60
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair	82,80
--	-------



Rearview mirror R complete, Broken, E - Replace	168,00
---	--------

