



## VOLKSWAGEN Golf: 1GPI139

Vinnumber:	<b>WVWZZZAUZEP572061</b>	Versionname:	<b>GOLF VAR Trendline 105PK</b>
First Registrationdate:	<b>25/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>120063</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1314</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>No Tow bar</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 2 mm</b>	Fr.R.	<b>Michelin: 2 mm</b>
	Re.L.	<b>Michelin: 2 mm</b>	Re.R.	<b>Michelin: 2 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	1134,10
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Backrest cover F L, Worn, Acceptable

0,00

*No pictures to display*

Bodywork, Not original part, Acceptable

0,00

*No pictures to display*

Wheel cover F R, Scratch(es), E - Replace

30,00



Rear window, Scratch(es), E - Replace

370,00

