



## VOLVO V40: 1GHX538

Vinnumber:	<b>VV1MV8481E2137611</b>	Versionname:	<b>V40 D2 Base 115PK</b>
First Registrationdate:	<b>12/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>145580</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3116</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Panoramic roof	
GPS storage	<b>HD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

<b>205/55/16/91 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Vredestein: 7 mm</b>	Fr.R.	<b>Vredestein: 7 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	348,00
-------------------	--------

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Chemical polution, 67 - Polish 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

