



VOLKSWAGEN Transporter: 1DOU110

Vinnumber:	WV2ZZZ7HZCH125784	Versionname:	TRANSP.1000 COMBI SWB 84PK
First Registrationdate:	10/07/2012	Fiscalpower:	
Expertise Mileage:	205121	Power Kw:	62
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	LCV05
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	8		
Number head rests:	8		
Rims summer:	Steel		
Category:	VS		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining artificial leather
Type of climate control	No climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/105 T Steel			
Summer tyres:	Fr.L. Uniroyal: 5 mm	Fr.R. Uniroyal: 5 mm	
	Re.L. Uniroyal: 7 mm	Re.R. Uniroyal: 7 mm	

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2934,14
-------------------	----------------

Interior, Stain, Cleaning	130,00
---------------------------	---------------



Roof, Rust, LI - Repair and paint (complete)	577,80
--	---------------



Backrest cover R R, Tear, E - Replace

408,00



Bumper F, Dent(s), E - Replace

579,84



Tailgate, Dent(s), LI - Repair and paint (complete)

362,02



Internal Boot Lining R, Scratch(es), E - Replace

150,00



Rearlight R , Crack, E - Replace

132,00



Dashboard, Hole, Smart repair

110,64



Bumper R, Dent(s), E - Replace

483,84



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Maintenance, Maintenance, Execute

0,00

