



VOLKSWAGEN GOLF VII: 1LDJ097

Vinnumber:	WVWZZZAUZGW087149	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	27/08/2015	Fiscalpower:	
Expertise Mileage:	86061	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	SERVICE -800KM -34D	Parking lot:	3413
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1185,13
-------------------	----------------

Wheel cover F R, Missing, E - Replace	30,00
---------------------------------------	--------------



Foglight L, Crack, E - Replace

138,00



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F R, Stain, Cleaning

25,00



Maintenance, Maintenance, Execute

0,00



Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar L, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Wheel cover F L, Missing, E - Replace

30,00



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80





Seat cover F L, Stain, Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

