



AUDI Q5: 1HXJ321

Vinnumber:	WAUZZZ8R7FA048065	Versionname:	Q5 Quattro clean S-tr.163PK Aut.
First Registrationdate:	21/10/2014	Fiscalpower:	
Expertise Mileage:	62663	Power Kw:	120
Bodytype:		Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2829
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/108 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 4 mm	Fr.R.	Semperit: 4 mm
	Re.L.	Semperit: 4 mm	Re.R.	Semperit: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1572,87
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	526,02



Door moulding Lower R R, Scratch(es), Smart repair

110,64



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

417,84



Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21

