



**AUDI A4: 1GKI167**

Vinnumber:	<b>WAUZZZ8K1EA108147</b>	Versionname:	<b>A4 AVANT TDi Multitr.136PK Aut.</b>
First Registrationdate:	<b>3/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>92656</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3101</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/16/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Emergency spare wheel **Yes**

Total cost ex VAT	1163,68
Door F L, Scratch(es), LI - Repair and paint (complete)	318,35





Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18

