



BMW 3: 1JFJ395

Vinnumber:	WBA3K91030F936733	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	3/12/2014	Fiscalpower:	
Expertise Mileage:	94366	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	17000KM	Parking lot:	3808
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Type of Tow bar	Tow bar removable
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			58,80
Door R R, Dent(s), Acceptable			0,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Seat cover F L, Worn, Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), 67 - Polish

0,00



Bumper F, Scratch(es), Acceptable

0,00



Windscreen, Stone chip(s), Windscreen repair

58,80



Door R L, Scratch(es), 67 - Polish

0,00



Door F R, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00



Ignition key, Worn, Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00

