



CITROEN C3 Picasso: 1HBR410

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | VF7SH5FS8ET520310 | Versionname: | C3 PICASSO Exclusive BMP 120PK Aut. |
| First Registrationdate: | 12/06/2014 | Fiscalpower: | |
| Expertise Mileage: | 30059 | Power Kw: | 88 |
| Bodytype: | | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3706 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|-------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Panoramic roof | |
| Windows electric F | | Central consol F | |
| Windows electric R | | Luggage cover | |
| Cruise Control | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 195/55/16/91 T LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | |
|-----------------------|------------|
| Emergency spare wheel | Yes |
|-----------------------|------------|

Total cost ex VAT 1037,18

Wing R R, Scratch(es), LI - Repair and paint (complete) 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

232,06



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Door moulding Lower R R, Scratch(es), E - Replace

96,00

