



BMW X4: KL6124

Vinnumber:	WBAXX110X00R35957	Versionname:	2.0 XDRIVE20D (140KW) 4WD
First Registrationdate:	8/09/2015	Fiscalpower:	
Expertise Mileage:	91335	Power Kw:	140
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3833
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/17/99 H LightMetal				
Winter tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1420,44
-------------------	----------------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>	
-------------------------------	--

Windscreen, Crack, E - Replace	560,64
--------------------------------	---------------



Door F R, Dent(s), PDR - Paintless dent repair

63,00



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

577,80



Protection plate M, Tear, E - Replace

124,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

