



VOLKSWAGEN PASSAT VARIANT: 1KHH023

Vinnumber:	VWVZZZ3CZFE454488	Versionname:	2.0 TDI VARIANT COMFORTLINE
First Registrationdate:	5/05/2015	Fiscalpower:	
Expertise Mileage:	179408	Power Kw:	110
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3609
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/45/18/98 V LightMetal			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	444,16
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Bad repair, LI - Repair and paint (complete) 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display 0,00


Door R L, Repaired, Acceptable 0,00

No pictures to display 0,00

Door R R, Repaired, Acceptable 0,00

No pictures to display 0,00

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Bad repair, LI - Repair and paint (complete) 0,00

