



**OPEL Vivaro 2700: 1JRT801**

Vinnumber:	<b>W0L4J7700FV613544</b>	Versionname:	<b>VIVARO 2700 COMBI L1H1 Edition 90PK</b>
First Registrationdate:	<b>10/02/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>105348</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>NOT OK</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>No</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>9</b>		
Number head rests:	<b>8</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>

**Limited Technical Inspection**

Airco functioning:	<b>NOT OK</b>	Battery functioning:	<b>No</b>
Tires wear profile:	<b>NOT OK</b>	Power steering:	<b>No</b>
Idle position:	<b>NOT OK</b>	Sound engine:	<b>NOT OK</b>
Engine startingtime:	<b>NOT OK</b>	Clutch test:	<b>NOT OK</b>
Exhaust gass:	<b>NOT OK</b>	Wiper fluid level:	<b>NOT OK</b>
Handbrake:	<b>NOT OK</b>	Transmission:	<b>NOT OK</b>
		Lighting:	<b>NOT OK</b>
		Wiperblades:	<b>NOT OK</b>

**Degree of wear**

	<b>205/65/16/107 T Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
--------------	------------	-------	------------

Total cost ex VAT:	<b>0,00</b>
--------------------	-------------

Bodywork, Accident, No repair:	<b>0,00</b>
--------------------------------	-------------

