



SKODA OCTAVIA COMBI: 1LNE906

Vinnumber:	TMBLG7NE7G0102153	Versionname:	1.6 CRTDI 81KW 4WD GREENTEC AMBITION
First Registrationdate:	27/10/2015	Fiscalpower:	
Expertise Mileage:	179223	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2304
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H Steel				
Winter tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1158,68
Seat cover F L, Stain, Acceptable	0,00



Seat cover R L, Stain, Acceptable

0,00



Seat cover F R, Stain, Acceptable

0,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00



Sill outer L, Scratch(es), LI - Repair and paint (complete)

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wheel cover R R, Scratch(es), Acceptable

0,00



Door R R, Dent(s) and scratch(es), Acceptable

0,00





Wheel cover R L, Scratch(es), E - Replace

30,00



Tailgate, Dent(s), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Trunk lid covering R, Scratch(es), Acceptable

0,00



Outer door handle R R, Scratch(es), Acceptable

0,00



Wheel cover F R, Scratch(es), E - Replace

30,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Wheel cover F L, Scratch(es), E - Replace

30,00



Wing F L, Scratch(es), Acceptable 0,00



Rearview mirror housing L, Stone chip(s), Acceptable 0,00



Bonnet, Dent(s), Acceptable 0,00

