



MERCEDES CLA: 1JLJ201

Vinnumber:	WDD1173121N166876	Versionname:	CLA BER 180 CDI 109PK
First Registrationdate:	16/01/2015	Fiscalpower:	
Expertise Mileage:	132791	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4815
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

25/40/18/92 V LightMetal				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	675,00
Seat cover F L, Stain, Cleaning	25,00



Seat cover F L, Worn, Acceptable

0,00



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Repaired, P - Check

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover R, Stain, Cleaning

50,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Repaired, P - Check

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Rearview mirror R complete, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar L, Bad repair, LI - Repair and paint (complete)

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover F R, Stain, Cleaning

25,00



Tyre F R, Tear, E - Replace

132,00

