



MERCEDES B: 1JGK230

Vinnumber:	WDD2462121J299571	Versionname:	B 180 CDI 109PK
First Registrationdate:	11/12/2014	Fiscalpower:	
Expertise Mileage:	174400	Power Kw:	80
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2103
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	195/65/15/91 T Steel			
	Fr.L.	Fulda: 4 mm	Fr.R.	Fulda: 4 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			210,53
Wheel cover F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Compressor, Missing, E - Replace			0,00
<i>No pictures to display</i>			
Bumper R, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Tyre repair kit, Missing, E - Replace			210,53

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display