


VOLKSWAGEN Polo: 1GRY587

Vinnnummer:	WVWZZZ6RZEY243371	Versionname:	POLO BlueMotion Techn.DPF 90PK
First Registrationdate:	11/04/2014	Fiscalpower:	
Expertise Mileage:	178157	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3612
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/60/5/84 T Steel				
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			280,44
Wing R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Seat cover F L, Stain, Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover F R, Scratch(es), E - Replace			24,00



Roof, Dent(s), PDR - Paintless dent repair 63,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 24,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Repaired, Acceptable 0,00

No pictures to display