



**VOLKSWAGEN Caddy: 1WDA508**

Vinnumber:	<b>WV2ZZZ2KZFX058188</b>	Versionname:	<b>CADDY MAXI LIFE Trendl.102PK OMBOUW Dub.</b>
First Registrationdate:	<b>24/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>169475</b>	Power Kw:	<b>75</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3502</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	Type of Tow bar
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>
	<b>Tow bar fixed</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V Steel</b>				
Summer tyres:	Fr.L.	<b>Continental: 2 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 3 mm</b>	Re.R.	<b>Continental: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>465,52</b>
-------------------	---------------

Wheel cover F L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>410,02</b>
---	---------------





Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Supplementary brake lights, Broken, E - Replace	33,00



Door R L, Chemical polution, Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), E - Replace	22,50



Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	