



**VW Passat: 1UJN245**

|                         |                          |              |                  |
|-------------------------|--------------------------|--------------|------------------|
| Vinnumber:              | <b>WVWZZZ3CZJE218237</b> | Versionname: |                  |
| First Registrationdate: | <b>23/05/2018</b>        | Fiscalpower: |                  |
| Expertise Mileage:      | <b>12432</b>             | Power Kw:    |                  |
| Bodytype:               |                          | Body color:  | <b>Grey</b>      |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>   |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b> |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>NOT OK</b>    |
| Battery functioning:    | <b>Yes</b>               |              |                  |
| Number of doors:        | <b>5</b>                 |              |                  |
| Number of seats:        | <b>5</b>                 |              |                  |
| Number head rests:      | <b>5</b>                 |              |                  |
| Rims summer:            | <b>Aluminium</b>         |              |                  |
| Category:               | <b>Passenger Car</b>     |              |                  |
| Oil level:              | <b>NOT OK</b>            |              |                  |

**Options**

|                       |                           |
|-----------------------|---------------------------|
| Type of headlighting: | <b>Headlighting Xenon</b> |
| Type of Lining:       | <b>Lining fabrics</b>     |

**Limited Technical Inspection**

|                     |               |                     |               |
|---------------------|---------------|---------------------|---------------|
| Airco functioning   | <b>NOT OK</b> | Battery functioning | <b>Yes</b>    |
| Tires wear profile  | <b>NOT OK</b> | Power steering      | <b>No</b>     |
| Idle position       | <b>NOT OK</b> | Sound engine        | <b>NOT OK</b> |
| Engine startingtime | <b>NOT OK</b> | Clutch test         | <b>NOT OK</b> |
| Exhaust gass        | <b>NOT OK</b> | Wiper fluid level   | <b>NOT OK</b> |
| Handbrake           | <b>NOT OK</b> | Transmission        | <b>NOT OK</b> |
|                     |               | Lighting            | <b>NOT OK</b> |
|                     |               | Wiperblades         | <b>NOT OK</b> |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/60/16/99 T LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 0 mm</b> | Fr.R. | <b>Michelin: 0 mm</b> |
|               | Re.L.                            | <b>Michelin: 0 mm</b> | Re.R. | <b>Michelin: 0 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                               |             |
|-------------------------------|-------------|
| Total cost ex VAT             | <b>0,00</b> |
| Bodywork, Accident, No repair | <b>0,00</b> |



