



BMW 1: 1JKN106			
Vinnumber:	WBA1C910X0P874987	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	12/01/2015	Fiscalpower:	
Expertise Mileage:	48871	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3405
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			3367,92
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)			366,35



Bumper F, Dent(s) and scratch(es), Le - Replace and paint 735,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 651,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 342,35



Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Seat cover R R, Stain, Cleaning 15,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), Le - Replace and paint 530,02



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 380,20



Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

