


**AUDI A5: 1HCS816**

Vinnumber:	<b>WAUZZZ8TXFA000975</b>	Versionname:	<b>A5 SB TDie DPF 136PK</b>
First Registrationdate:	<b>19/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>136300</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3806</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/94 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>473,60</b>
Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Interior, Dirty, Cleaning	50,00
---------------------------	-------



Window R L door, Not original part, Acceptable	0,00
--	------



Door R R, Bad repair, Acceptable	0,00
----------------------------------	------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Dent(s), LI - Repair and paint (complete)	211,80
---	--------

