



**BMW 3: 1HG214**

Vinnumber:	<b>WBA3D91000J414505</b>	Versionname:	<b>3 BER 316d 116PK</b>
First Registrationdate:	<b>15/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>56678</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4325</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	<b>HD</b>	Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 W LightMetal</b>			
Summer tyres:	Fr.L. <b>Pirelli: 5 mm</b>	Fr.R. <b>Pirelli: 5 mm</b>	
	Re.L. <b>Pirelli: 6 mm</b>	Re.R. <b>Pirelli: 6 mm</b>	

**Assistance equipment**

Runflat	<b>Yes</b>
---------	------------

Total cost ex VAT	<b>158,00</b>
-------------------	---------------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Ignition key, Missing, E - Replace 0,00

